



Circuits and design information are offered only as suggestions and are furnished free of charge. This company and its agents assume no liability for errors nor for the safe and/or satisfactory operation of machines or systems designed from this information.

Furnaces begin to leak over time to the point where it may affect part quality. Monitoring the volume of air for each shot with the F-Series Flow Monitor allows you to determine when your leaks are too great before you generate a bad part. It also allows you to detect leaks early and reduce expensive wasted air.

PROPORTION-AIR	
DESCRIPTION	
Shot Air Volume	
DRAWN BY	Lpd
DRAW DATE	2/16/05
DRAWING #	DWEBL083A