


Flow

Circuits and design information are offered only as suggestions and are furnished free of charge. This company and its agents assume no liability for errors nor for the safe and/or satisfactory operation of machines or systems designed from this information.



**Application:** PRESSURE CONTROL IN A DIECAST FURNACE

Many die cast processes use pressure to force alloy into a mold. In most cases pressure is profiled on both the increase and decrease phases. Since exhaust gas is hot, an FCV is used for exhaust phase.

<b>DESCRIPTION</b>	Pressure Control in Diecast Furnace
<b>DRAWN BY</b>	lpd
<b>DRAW DATE</b>	5/13/03
<b>DRAWING #</b>	<b>DWEBL35A</b>